

DESPESAS COM MANUTENÇÃO DE VEÍCULOS

Mês: Março/2020

Placa	Modelo	Total
AVQ-3044	FLUENCE	55,00
AVQ-3064	FLUENCE	55,00
AVQ-3075	FLUENCE	55,00
AVQ-3806	FLUENCE	1.199,00
AVQ-4392	FLUENCE	78,00
AVQ-8265	FLUENCE	35,00
AVQ-8446	FLUENCE	244,20
AVQ-8449	FLUENCE	55,00
AVU-7825	FLUENCE	495,00
AVX-9244	FLUENCE	55,00
AVX-9519	FLUENCE	55,00
AVY-6904	FLUENCE	440,00
AVY8902	FLUENCE	55,00
AWB-5913	FLUENCE	35,00
AWF8760	FLUENCE	55,00
AWF-8766	FLUENCE	55,00
AWF-8771	FLUENCE	55,00
AWF-8859	FLUENCE	55,00
MII-8726	LOGAN	3.622,76
MIL-3126	LOGAN	1.602,00
MIR-8466	LOGAN	430,96
MIY-6965	LOGAN	30,00
MIY-7065	LOGAN	1.220,00
MIY-7925	LOGAN	467,00
MIY-8215	LOGAN	35,00
MJB-2785	LOGAN	512,00
MJB-3125	LOGAN	241,00
MJD-3228	FLUENCE	55,00
MJD-9205	FUSION	330,20
MJG-3927	LOGAN	410,00
MJX-8178	FLUENCE	23,00
MJX-8248	FLUENCE	405,00
MKU-5877	EDGE LIMITED	339,30
MLM-6532	FREEMONT	12.000,00
MLN-2439	FLUENCE	55,00
MLN-6847	FIESTA SEDAN	350,00
MLO-8297	FIESTA SEDAN	50,00
MOT-0010	GERADOR	418,00
OKD-9616	TRAILBLAZER	60,00
OKG-3877	SPIN LT	283,00
OKG-6997	SPIN LT	55,00
OKG-7117	SPIN LT	55,00
QHA-8751	FREEMONT	55,00
QHG-8918	LOGAN	230,00
QHI-5513	PEUGEOT 408	265,90

QHI-5683	PEUGEOT 408	418,00
QHO-7876	LOGAN	55,00
QIY-7079	C4 LOUNGE	55,00
QJF-4614	C4 LOUNGE	623,00
QJH-3863	KIA SORENTO	55,00
QJK-5504	TRAILBLAZER	55,00
QTL-8048	SPIN LT	55,00
QTL-8658	SPIN LT	55,00
TOTAL		28.102,32